DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012869 Address: 333 Burma Road **Date Inspected:** 18-Mar-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Liu Hua Jie **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Bay 14:

This QA Inspector observed the following work in progress:

Flux Cored Arc Welding (FCAW) of weld joint SEG3005*-002 (for 12BW). Welder was identified as 201215. ZPMC Quality Control (QC) is identified as Liming Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2231-B-U2-F.

Submerged Arc Welding (SAW) of weld joint SEG3003* - 003 (for 12 CE). Welder was identified as 044771. ZPMC Quality Control (QC) is identified as Liming Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2221-B-L2C-S2.

Outside Yard:

CB10.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed ABF Personnel, identified as Mr. Cao Hui Zhao, marking areas to be repaired on weld no: CB202A-010 - 017. This weld has been rejected by Contractors UT Personnel. This QA Inspector verified the locations marked for repair as per UT report no: UT-CB10-001 & Critical Weld Repair Report (CWR) No: B-CWR999 Rev-0, Dt: 12/31/09.

No other significant work was being performed on this CB at the time when this QA was present.

CB8:

Notification No: 005368.

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector has generated MT report for this date. The member(s) are identified as OBG components. The weld designations reviewed are as follows:

- 1) FB204-017 071, 072, 077 to 080, 085, 086, 007, 008, 016, 017, 026, 029, 044, 047.
- 2) FB204-018 071, 072, 077 to 080, 085, 086, 007, 008, 016, 017, 026, 029, 044, 047.
- 3) FB204-019 071, 072, 077 to 080, 085, 086, 007, 008, 016, 017, 026, 029, 044, 047.
- 4) FB204-020 071, 072, 077 to 080, 085, 086, 007, 008, 016, 017, 026, 029, 044, 047.
- 5) SP205A-008 015 to 018.
- 6) SP206A-008 009 to 014.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar, Sailesh	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer